SEALED-BLOK™
WITH FAST-LINE™ SRL

FAST-Line Means LIFETIME

Saves Time, Money and Productivity

TTT Environmental & Safety
Instruments and Supplies

The preferred source for instrument Rentals, Sales, Service and Supplies!

Anchorage	Seattle	Fairbanks
(907) 770-9041	(253) 373-9041	(907) 374-9040

DBI SALA®

THE ULTIMATE IN FALL PROTECTION

PRODUCT SHEET

SEALED-BLOK™
WITH FAST-LINE™ SRL

THE BENEFITS OF THE SEALED-BLOK WITH FAST-LINE SRL KEEP GETTING BETTER!

Owners of Sealed-Blok with FAST-Line SRLs with a date of manufacture after January 4, 2015 are no longer required to send their FAST-Line SRLs back to Capital Safety for recertification in the event of a fall or if the impact indicator has activated.

Some competitors require you to change the internal brake of their SRLs after a fall. But our Sealed Blok with FAST-Line SRL uses a proven brake technology that does not require replacement after a fall.

BENEFITS OF THIS NEW FEATURE INCLUDE:

- **Reduce downtime with the quick FAST-Line replacement time**
- **Lower lifetime expenses and save money**
  - Replacement cables are much less expensive than a brake mechanism
  - Shipping costs to have the SRL serviced are reduced or eliminated
- **Maximize productivity**

Customers who purchased Sealed-Bloks with FAST-Line prior to January 4, 2015 may have their SRLs certified for this program by an authorized Capital Safety service center for a one-time Level 2 Service Fee. It will then be given a new label indicating it can be serviced in the field.



TO COMPLY WITH THIS PROGRAM, FOLLOW THESE EASY STEPS:

1. Determine whether or not your Sealed-Blok SRL can be field serviced after a fall. Look for the box with a check mark on our new label signifying this capability.
2. Replace the cable and hook (the FAST-Line) in the field in accordance with the IFU.

A. Pull entire length of cable out and activate lock to prevent rewinding.

B. Loosen original cable termination and remove lifeline assembly.

C. Insert new lifeline assembly and secure in place. Restrain lifeline, release lock and allow new lifeline to retract.

3. Complete inspection by a competent person in accordance with the IFU.
4. Return the Sealed-Bok with FAST-Line SRL to service.

See how easy it is to replace the FAST-Line

Capital Safety
USA: 800 328 6146
www.capitalsafety.com info@ capitalsafety.com

@Capital_Safety Facebook.com/CapitalSafety

©2015, Capital Safety Form 9701364 Rev B